

9F	9 to 13½ Picas: 8½ to 12½ Ciceros				
	Column Support, No. 4				
9F1	Bar (Not supplied separately, order X9F)				
9F2	Bar Finger Catch				
9F3	Bar Finger Catch Screw (2), $\frac{3}{32}'' \times \frac{7}{64}''$, countersunk				
9F4	Slide (Not supplied separately, order X9F)				
9F5	Slide Plate (Not supplied separately, order X9F)				
9F6	Slide Finger Catch				
9F7	Slide Finger Catch Rivet				
9F8	Slide Stop Pin				
9F9	Spring				
9F10	Spring Guide Rod (Not supplied separately, order X9F)				
X9F	Column Support, No. 4, group; consists of 9F1 and 2, 9F3(2), 9F4 to 10 inclusive				
10F	13½ to 20 Picas: 12½ to 18½ Ciceros				
	Column Support, No. 5				
10F1	Bar (Not supplied separately, order X10F)				
10F2	Bar Finger Catch				
10F3	Bar Finger Catch Screw (2), $\frac{3}{32}'' \times \frac{7}{64}''$, countersunk				
10F4	Slide (Not supplied separately, order X10F)				
10F5	Slide Plate (Not supplied separately, order X10F)				
10F6	Slide Finger Catch				
10F7	Slide Finger Catch Rivet				
10F8	Slide Stop Pin				
10F9	Spring				
10F10	Spring Guide Rod (Not supplied separately, order X10F)				
X10F	Column Support No. 5, group; consists of 10F1 and 2, 10F3(2), 10F4 to 10 inclusive				
11F	20 to 30 Picas: 18½ to 28 Ciceros				
	Column Support, No. 6				
11F1	Bar (Not supplied separately, order X11F)				
11F2	Bar Finger Catch				
11F3	Bar Finger Catch Screw (2), $\frac{3}{32}'' \times \frac{7}{64}''$, countersunk				
11F4	Slide (Not supplied separately, order X11F)				
11F5	Slide Plate (Not supplied separately, order X11F)				
11F6	Slide Finger Catch				
11F7	Slide Finger Catch Rivet				
11F8	Slide Stop Pin				
11F9	Spring				
11F10	Spring Guide Rod (Not supplied separately, order X11F)				
X11F	Column Support, No. 6, group; consists of 11F1 and 2, 11F3(2), 11F4 to 10 inclusive				
29F					
	Line Support (up to and including 8 didot)				
29F1	Spring				
a29F1	Spring, Quadding and Centring Attachment				
29F2	Spring Screw, $\frac{1}{16}'' \times \frac{3}{32}''$, Quadding and Centring Attachment				
a29F2	Pin, for Spring				
29F6	Guide (Not supplied separately, order Xe29F, Xf29F or Xp29F)				
29F7	Guide Rivet (2)				
29F8	Plate Trip				
29F9	Plate Rivet (2)				
Xe29F	Line Support, thin, 9 to 24 Pica and 9 to 23 Cicero, Quadding and Centring Attachment, group; consists of e29F, a29F1, 29F2, 29F6, 29F7(2) (see Plate 49)				
Xf29F	Line Support, thin, 24 to 60 Pica and 23 to 56 Cicero, Quadding and Centring Attachment, group; consists of f29F, a29F1, 29F2, 29F6, 29F7(2) (see Plate 49)				
Xh29F	Line Support, thin, group; consists of h29F, 29F1, a29F2				
Xj29F	Line Support, thin, 6 to 7 point inclusive, Reverse Delivery Attachment, group; consists of j29F, 29F1, a29F2				
Xk29F	Line Support, thin, 5 to 8 point inclusive, Galley Trip (Sorts) Attachment, group; consists of k29F, 29F1, a29F2 (see Plate 44)				
Xm29F	Line Support, thin, 5 to 8 point inclusive, Galley Trip (Sorts) Attachment, group; consists of m29F, 29F1, a29F2				
Xn29F	Line Support, thin, Leading Attachment, group; consists of n29F, 29F1, a29F2 (see Plate 47)				
Xp29F	Line Support, thin (also Trip for Galley), 5 to 8 point inclusive, Galley Trip (Sorts) Attachment, group; consists of p29F, a29F1, 29F2, 29F6, 29F7(2), 29F8, 29F9(2)				
30F					
	Line Support (9 point and over)				
30F1	Spring				
a30F1	Spring, Quadding and Centring Attachment				
30F2	Spring Screw, $\frac{1}{16}'' \times \frac{3}{32}''$, Quadding and Centring Attachment				
a30F2	Pin, for Spring				
30F6	Guide (Not supplied separately, order Xe30F, Xf30F, Xp30F, Xu30F, Xbw30F, Xdw30F or Xew30F)				
30F7	Guide Rivet (2)				
30F8	Facing (Not supplied separately, order Xe30F or Xu30F)				
a30F8	Facing (Not supplied separately, order Xbw30F, Xdw30F or Xew30F)				
30F9	Facing Rivet (3), for 30F8				
a30F9	Facing Rivet (3), for a30F8				
30F10	Plate, Trip				
30F11	Plate Rivet (2)				
Xe30F	Line Support, thick, 9 to 24 pica and 9 to 23 cicero, Quadding and Centring Attachment, group; consists of e30F, a30F1, 30F2, 30F6, 30F7(2), 30F8, 30F9(3) (see Plate 49)				
Xf30F	Line Support, thick, 24 to 60 pica and 23 to 56 cicero, Quadding and Centring Attachment, group; consists of f30F, a30F1, 30F2, 30F6, 30F7(2) (see Plate 49)				
Xh30F	Line Support, thick, group; consists of h30F, 30F1, a30F2				
Xj30F	Line Support, thick, 8 to 12 point inclusive, Reverse Delivery Attachment, group; consists of j30F, 30F1, a30F2				
Xk30F	Line Support, thick, 9 to 12 point inclusive, Galley Trip (Sorts) Attachment, group; consists of k30F1, 30F1, a30F2 (see Plate 44)				
Xm30F	Line Support, thick, 9 to 12 point inclusive, Galley Trip (Sorts) Attachment, group; consists of m30F, 30F1, a30F2				
Xn30F	Line Support, thick, Leading Attachment, group; consists of n30F, 30F1, a30F2 (see Plate 47)				
Xp30F	Line Support, thick (also Trip for Galley), 9 to 12 point inclusive, Galley Trip (Sorts) Attachment, group; consists of p30F, a30F1, 30F2, 30F6, 30F7(2), 30F10, 30F11(2)				
Xq30F	Line Support, thick, 9 point and didot and over, Duplex Mould Attachment, group; consists of q30F, 30F1, a30F2				
Xu30F	Line Support, thick, 9 point and didot and over, 9 to 24 pica, 9 to 23 cicero, Duplex Mould Attachment, group; consists of u30F, a30F1, 30F2, 30F6, 30F7(2), 30F8, 30F9(3)				
Xv30F	Line Support, thick, Large Composition Attachment, group; consists of v30F, 30F1, a30F2				
Xw30F	Line Support, thick, Large Composition Attachment, group; consists of w30F, 30F1, a30F2				
Xaw30F	Line Support, thick, Large Composition Attachment, group; consists of aw30F, 30F1, a30F2				
Xbw30F	Line Support, thick, also Trip for Galley, Large Composition Attachment, group; consists of bw30F, a30F1, 30F2, 30F6, 30F7(2), a30F8, a30F9(3), 30F10, 30F11(2)				
Xew30F	Line Support, thick, Large Composition Attachment, group; consists of cw30F, 30F1, a30F2				
Xdw30F	Line Support, thick, 9 to 24 pica, 9 to 23 cicero, Large Composition Attachment, group; consists of dw30F, a30F1, 30F2, 30F6, 30F7(2), a30F8, a30F9(3)				
Xew30F	Line Support, thick, 24 to 60 pica, 23 to 56 cicero, Large Composition Attachment, group; consists of ew30F, a30F1, 30F2, 30F6, 30F7(2), a30F8, a30F9(3)				
Xfw30F	Line Support, Tripless Mould Attachment, group; consists of fw30F, 30F1, a30F2 (see Plate 57)				
52F	6 to 9 Picas: 6 to 8½ Ciceros				
	Column Support, No. 3				
52F1	Bar (Not supplied separately, order X52F)				
52F4	Slide (Not supplied separately, order X52F)				
52F5	Slide Plate (Not supplied separately, order X52F)				
52F8	Slide Stop Pin				
52F9	Spring				
52F10	Spring Guide Rod (Not supplied separately, order X52F)				
X52F	Column Support, No. 3, group; consists of 52F1, 52F4 and 5, 52F8, 9 and 10				
72F	3 to 4 Picas: 3 to 4 Ciceros				
	Column Support, No. 1				
72F1	Bar (Not supplied separately, order X72F)				
72F2	Slide (Not supplied separately, order X72F)				
72F3	Slide Plate (Not supplied separately, order X72F)				
72F4	Slide Plate Stop Pin				
72F5	Spring				
X72F	Column Support, No. 1, group; consists of 72F1 to 5 inclusive				
73F	4 to 6 Picas: 4 to 6 Ciceros				
	Column Support, No. 2				
73F1	Bar (Not supplied separately, order X73F)				
73F2	Slide (Not supplied separately, order X73F)				
73F3	Slide Plate (Not supplied separately, order X73F)				
73F4	Slide Stop Pin				
73F5	Spring				
X73F	Column Support, No. 2, group; consists of 73F1 to 5 inclusive				
211F					
	Line Support Pusher Spring Box				
a211F1*	Cap				
211F2	Keep Split Pin, $\frac{1}{16}'' \times \frac{1}{4}''$				
211F3	Pin, Anchor for Spring				
211F4	Position Pin, for Chain				
211F5	Spring				
211F6	Support				
211F7†	Support Cap				
211F8	Support Cap Screw (2), $\frac{1}{16}'' \times \frac{9}{16}''$ hexagon				
211F9	Support Pin, Anchor for Spring				
211F10‡	Washer				
211F11	Abutment				
211F12	Abutment Pin				
211F13	Abutment Screw, $\frac{1}{16}'' \times \frac{3}{8}''$, hexagon				
211F14	Stop Pin				
211F15	Line Support Pusher Spring Box group; consists of a211F1F, 211F2 and 3, 211F5 and 6, 211F7F, 211F8, 211F9(2), 211F11 to 14 inclusive				
Xa211F	*a211F1F consists of a211F1, a211F4, 211F15				
	†211F7F consists of 211F7, 211F10				
	‡Can be fitted only at Workshops				
212F					
	Line Support Pusher Spring Box Chain				
c212F1	Line Support Pusher Spring Box Chain, Quadding and Centring Attachment (see Plate 49)				
d212F1					